

Inspection Photos
Location Name: Jagged 4N64W08 1-12 Tank Battery
Facility ID: 481797



Location



Tank Battery

Inspection Photos
Location Name: Jagged 4N64W08 1-12 Tank Battery
Facility ID: 481797



Tank Battery



ECDs

Inspection Photos
Location Name: Jagged 4N64W08 1-12 Tank Battery
Facility ID: 481797



Pits



Separators

Inspection Photos
Location Name: Jagged 4N64W08 1-12 Tank Battery
Facility ID: 481797



LO/TO Separator for Maintenance



LO/TO Separator for Maintenance

Inspection Photos

Location Name: Jagged 4N64W08 1-12 Tank Battery

Facility ID: 481797



Bulk Separator



Air Compressor

Inspection Photos
Location Name: Jagged 4N64W08 1-12 Tank Battery
Facility ID: 481797



Lact



ECO Vapor

Inspection Photos

Location Name: Jagged 4N64W08 1-12 Tank Battery

Facility ID: 481797



VRU & Compressor



Gas meter runs

Inspection Photos
Location Name: Jagged 4N64W08 1-12 Tank Battery
Facility ID: 481797



No Capacity Label



No Capacity Label

Inspection Photos

Location Name: Jagged 4N64W08 1-12 Tank Battery

Facility ID: 481797



Inadequate netting



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources