

Inspection Photos
Location Name: Timbro 0101 PAD
Location ID: 468727



Photo 1 – Wellheads – Cellars not back filled in

Photo 2 – Compressors

Inspection Photos
Location Name: Timbro 0101 PAD
Location ID: 468727



Photo 3 – VRUs



Photo 4 – ECD

Inspection Photos
Location Name: Timbro 0101 PAD
Location ID: 468727



Energy and Carbon Management Commission
40.78693, -103.92558, 4897.5ft
05/21/2024 11:43:08



Energy and Carbon Management Commission
40.78678, -103.92562, 4889.7ft
05/21/2024 11:43:18

Photo 5 – Cooler

Photo 6 – Tank Battery

Inspection Photos
Location Name: Timbro 0101 PAD
Location ID: 468727



Photo 7 – LACTs

Photo 8 – Separators

Inspection Photos
Location Name: Timbro 0101 PAD
Location ID: 468727



Photo 9 – Separators

Photo 10 – Wellhead Headers

Inspection Photos
Location Name: Peanut Federal 3403 PAD
Location ID: 481827



Photo 11 – Wellheads



Photo 12 – Wellheads

Inspection Photos
Location Name: Peanut Federal 3403 PAD
Location ID: 481827



Photo 13 – Gas Meters



Photo 14 – Compressors

Inspection Photos
Location Name: Peanut Federal 3403 PAD
Location ID: 481827




Photo 15 – Sign at Entrance