

# Final Reclamation and Stormwater Inspection

Date: 05/29/2024

Operator: MCCARTNEY ENGINEERING LLC - 55030

Location ID: 320429

Inspection Document #: 708201278

Adams County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: HSR-Fulenwider 12-10  
Location ID: 320429



**Photo 1.** Facing north; the former wellhead area has subsided approximately 2-3' bsg. Additional reclamation activities are required to return the area to existing grade.

Inspection Photos  
Location Name: HSR-Fulenwider 12-10  
Location ID: 320429



**Photo 2.** Facing east; see comments in Photo 1.

Inspection Photos  
Location Name: HSR-Fulenwider 12-10  
Location ID: 320429



**Photo 3.** Facing south; see comments in Photo 1.

Inspection Photos  
Location Name: HSR-Fulenwider 12-10  
Location ID: 320429



**Photo 4.** Facing west; see comments in Photo 1.