



Advanced Technologies  
Waste Management Support  
Environmental Services  
Staff Augmentation

Native American and Women Owned  
8(a) Small Business

April 26, 2024  
Sydney Smith  
Fundare Resource Company  
56719 CR 127  
New Raymer, CO 80742  
**RE: Liner Inspection**  
**Razor 12F**  
**Weld County, Colorado**

Sydney:

On April 25, 2024, MarCom LLC (MarCom) was contracted by Fundare to conduct a site inspection at the Razor 10E release and complete a liner inspection at the (Site) in Weld County, Colorado. The purpose of the inspection event was to ensure that all hydrocarbon released were contained and did not leave the containment. The site is identified by the COGCC as Facility ID 438566.

On April 25, 2024, Following the removal of the Pea Gravel, MarCom personnel conducted a full liner inspection of the containment surrounding the Razor 110E release. The inspector found a clean liner with no signs of damage, and the overall integrity of the liner was in good shape. A photo doc attached shows the liner and containment.

Following the removal of the Pea Gravel Fundare contractors transported and disposed of the material at an approved landfill facility. Clean Pea Gravel will be brought into the containment upon approval of this closure request. Based upon the inspection MarCom believes that no impacts left the containment, and no further corrective action is necessary, and that Fundare can request closure from the COGCC. If you have any questions or comments, please do not hesitate to call me at (970) 237-1415.

Respectfully Submitted,  
Levi Kirk  
Project Manager  
MarCom LLC

**Idaho Falls, ID**  
525 Park Avenue, Suite 2E  
Idaho Falls, ID 83402  
Phone: 208-538-1782

**Butte, MT**  
65 E Broadway, Suite 200  
Butte, MT 59701  
Phone: 208-390-8301

**Fort Collins, CO**  
1811 E. Mulberry Street  
Fort Collins, CO 80524  
Phone: 208-201-8280

<https://www.marcom-services.com/>



Where Technical Expertise Meets Environmental Solutions

Fundare

Razor 10E Photo Doc

Drafted By: Levi Kirk



Photo Date 4/25/2024- Area where impacts were discovered on North side of containments.



Photo Date 4/25/2024- Exterior of containment.



Photo Date 4/25/2024- Interior of containment with Liner in good shape.



Photo Date 4/25/2024- Interior of containment with Liner in good shape.



Photo Date 4/25/2024- Interior of containment with Liner in good shape in areas where release occurred.