

Interim Reclamation and Stormwater Inspection

May 30, 2024

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 440281

Inspection Document #: 697505318

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources




Photo 1. Aerial imagery from 2021 illustrates the location has not been interim reclaimed.

Inspection Photos
Location Name: NGL C9C
Location ID: 440281



Photo 2. Photo taken from the entrance of location, facing East. Photo illustrates the Operator sign.



Photo 3. Photo taken from the well location entrance, facing Southeast. Photo illustrates the shed over the wellhead.

Inspection Photos
Location Name: NGL C9C
Location ID: 440281



Photo 4. Photo taken of the southeastern location, facing East. Photo illustrates the cut slope that has not been interim reclaimed.



Inspection Photos
Location Name: NGL C9C
Location ID: 440281



Photo 5. Photo taken of the northwestern location, facing North. Photo illustrates the fill slope that has not been interim reclaimed.



Inspection Photos
Location Name: NGL C9C
Location ID: 440281



Photo 6. Photo taken of the northern location, facing East. Photo illustrates the topsoil stockpile that has weedy vegetation.

