

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 5/23/2024



Location Entrance – Photo #01355



Wellheads – Photo #01357



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 5/23/2024



Separators – Photo #01360




Storage Tank – Photo #01356

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 5/23/2024



Storage Tank – Photo #01367



Tank Battery – Photo #01365



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 5/23/2024



Stored Supplies/Equipment – Photo #01358



Stored Supplies/Equipment – Photo #01362



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 5/23/2024



Stored Supplies/Equipment – Photo #01363



Stored Supplies/Equipment – Photo #01364

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 5/23/2024



**Unprotected Soil Stockpile – Photo #01359**