

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33NESE

Location ID: 335267

Date: 5/24/2024



Wellheads – Photo #01415



Separators – Photo #01418

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33NESE

Location ID: 335267

Date: 5/24/2024



Tank Battery – Photo #01420



Weathered Wellhead Sign – Photo #01416

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33NESE

Location ID: 335267

Date: 5/24/2024



Weathered Wellhead Sign – Photo #01417