

Operator: HIGHPOINT OPERATING CORPORATION
Location Name: Anschutz Equus Farms 4-62-20_21 SWNW
Loc ID: 444717
Inspection: 713900517

HighPoint 1-800-880-6359
RESOURCES EMERGENCY ONLY

**ANSCHUTZ EQUUS FARMS 4-62-20_21 SWNW FACILITY
SWNW SEC20 T4N R62W
BATTERY ID 19584D
WELD COUNTY, CO**

ANSCHUTZ EQUUS FARMS 4-62-20-3225D2
NWNW SEC20 T4N R62W
API 05-123-42711

ANSCHUTZ EQUUS FARMS 4-62-20-1724B2
NWNW SEC20 T4N R62W
API 05-123-42713

ANSCHUTZ EQUUS FARMS 4-62-20-0108B2
NWNW SEC20 T4N R62W
API 05-123-42715

ANSCHUTZ EQUUS FARMS 4-62-20-0108C2B
NWNW SEC20 T4N R62W
API 05-123-42709

ANSCHUTZ EQUUS FARMS 4-62-20-1609C2
NWNW SEC20 T4N R62W
API 05-123-42710

HWY 34 SE 19.7 MI, S 0.5 MI, W 0.25 MI, N 0.25 MI INTO
LAT 40° 17' 58.5708", LONG -104° 21' 22.9392"

Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: This location does not comply with Reclamation rules. Rule 1002.c. states all stockpiled soil shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Best management practices to prevent weed establishment and to maintain soil microbial activity shall be implemented. Topsoil stockpile has significant weed cover- Russian thistle- with no perennial vegetation that would compete with the weedy vegetation and generally work to decrease weed growth. Best management practices to prevent weed establishment shall be implemented. Control, Date manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

CA Resolution: Operator has provided photo documentation to show that the location has been appropriately mowed to address any weeds and undesirable vegetation. The area has been seeded, and straw crimped to provide stabilization and promote more uniform future growth. Location currently complies with Rule 1002.c.

CA: It appears the Operator has performed interim reclamation activities and stabilization; however, interim areas are dominated by Russian thistle with no germination of desirable perennial vegetation. In addition, the wells associated with the location have been abandoned and therefore the location production pad should be reduced to only areas needed for production and the remaining should be interim reclaimed. Perform reclamation on areas not needed for production as well as current interim areas in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

CA Resolution: Operator has provided photo documentation to show that the location has been appropriately mowed to address any weeds and undesirable vegetation. The area has been seeded, and straw crimped to provide stabilization and promote more uniform future growth.. Location currently complies with Rule 1003.