

**Inspection Photos**  
**Location: Black Gold 32-33**  
**Facility ID: 309227**



**Photo 1 –Well placard**



**Photo 2 – Wellhead and equipment**



**Inspection Photos**  
**Location: Black Gold 32-33**  
**Facility ID: 309227**



**Photo 3 – Engine Skid**



**Photo 4 – Tank near meter house without cap**



**Inspection Photos**  
**Location: Black Gold 32-33**  
**Facility ID: 309227**



**Photo 5 – Unused equipment**



**Photo 6 – Pit Facility ID 301143, Pit closure in process, flowline to pit remains in place. Material in pit bottom does not match pit photos from 10/31/2023**



**Inspection Photos**  
**Location: Black Gold 32-33**  
**Facility ID: 309227**



**Photo 7 – Material in pit bottom does not match pit photos from 10/31/2023**



**Photo 8 – Pit Photo 10/31/2023**



**Inspection Photos**  
**Location: Black Gold 32-33**  
**Facility ID: 309227**



**Photo 9 – Pit Photo 10/31/2023**

