

**Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960**



Relief riser missing rain protection



Debris

**Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960**



Illegible label



Containment open to wildlife

**Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960**



Debris



Debris

Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960



Debris



Debris

**Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960**



Debris



Open end load line

**Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960**



Tank battery sign.



No tank battery sign

**Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960**



Berm undersize for size of tank



Berm not impervious to spilled fluids

**Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960**



Location from Southwest corner



Location from Southeast corner

**Robert L Bayless Producer LLC
Cottonwood Gulch Federal C-1
Location ID: 312960**



Location from Northeast corner



Location from Northwest corner