

Inspection Photos

API: 017-06632

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 5/30/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the access road. The access road was inaccessible due to water pooling on the road. The road needs to be built up with road base to allow proper stormwater drainage.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06632 | Date: 5/30/2024