

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWNE

Location ID: 334920

Date: 5/30/2024



Wellheads – Photo #01478



Separators – Photo #01483



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWN

Location ID: 334920

Date: 5/30/2024



Tank Battery – Photo #01484



Weathered/Illegible Wellhead Sign – Photo #01479




## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWNE

Location ID: 334920

Date: 5/30/2024



Weathered/Illegible Wellhead Sign – Photo #01480



Weathered/Illegible Wellhead Sign – Photo #01482