

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S. PARACHUTE FEDERAL-67S95W/28NWSW

Location ID: 334071

Date: 6/4/2024



Location Entrance – Photo #01507



North End of Pad – Photo #01508

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S. PARACHUTE FEDERAL-67S95W/28NWSW

Location ID: 334071

Date: 6/4/2024



Wellheads – Photo #01510



Separators – Photo #01512



## Inspection Photos


Location Name: CAERUS PICEANCE LLC, S. PARACHUTE FEDERAL-67S95W/28NWSW

Location ID: 334071

Date: 6/4/2024



**Tank Battery – Photo #01515**



**Gas Meter – Photo #01511**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S. PARACHUTE FEDERAL-67S95W/28NWSW

Location ID: 334071

Date: 6/4/2024



Open-Ended Line – Photo #01517



Open-Ended Line – Photo #01518



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S. PARACHUTE FEDERAL-67S95W/28NWSW

Location ID: 334071

Date: 6/4/2024



Open-Ended Line – Photo #01519



Open-Ended Line – Photo #01520



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, S. PARACHUTE FEDERAL-67S95W/28NWSW

Location ID: 334071

Date: 6/4/2024



Unprotected Soil Stockpile – Photo #01513



Unprotected Soil Stockpile – Photo #01514