

Inspection Photos
Location: Panhead 32-8
Location ID: 308865




Photo 1 – Well placard, WDID sticker not legible

Photo 2 – Wellhead

Inspection Photos
Location: Panhead 32-8
Location ID: 308865



Photo 3 – Tank near Meter House, re-place cap to prevent wildlife access

Photo 4 – Trees on sediment trap.

Inspection Photos
Location: Panhead 32-8
Location ID: 308865



Photo 5 – Access road, stormwater is bypassing the culvert