

Inspection Photos
Location: Champion 44-9 R
Location ID: 426430



Photo 1 –Well placard, WDID sticker not present

Photo 2 – Wellhead and equipment

Inspection Photos
Location: Champion 44-9 R
Location ID: 426430



Photo 3 – Tank near Meter House broken

Photo 4 - Tank near Meter House missing cap

Inspection Photos
Location: Champion 44-9 R
Location ID: 426430



Photo 5 – Leaking packing