

**Inspection Photos**  
**Location: Hobbs 14-10**  
**Location ID: 307586**



**Photo 1 –Well placard**

**Photo 2 – Wellhead and equipment**

Inspection Photos  
Location: Hobbs 14-10  
Location ID: 307586



Photo 3 – Impacted soils at meter house

Photo 4 – Stained soils at wellhead

**Inspection Photos**  
**Location: Hobbs 14-10**  
**Location ID: 307586**



**Photo 5 – Stained soils at engine skid**

**Photo 6 – Pit ID 113406, No freeboard marker present at the time of inspection**

**Inspection Photos**  
**Location: Hobbs 14-10**  
**Location ID: 307586**



**Photo 7 – Repair pit fencing to prevent livestock access**