

Inspection Photos
Location: Hill 33-22 and Hill 33-22 TR
Location ID: 334321



Photo 1 –Well placard



Photo 2 – Original Well and Equipment

Inspection Photos
Location: Hill 33-22 and Hill 33-22 TR
Location ID: 334321



Photo 3 – TR Well and equipment



Photo 4 – White staining around wellhead

Inspection Photos
Location: Hill 33-22 and Hill 33-22 TR
Location ID: 334321



Photo 5 – Pit ID 262363

