

**Inspection Photos**  
**Location: Silverland 31-22 and Silverland 31-22 TR**  
**Location ID: 334200**



**Photo 1 –Well placard**



**Photo 2 – Original Wellhead and equipment**



**Inspection Photos**  
**Location: Silverland 31-22 and Silverland 31-22 TR**  
**Location ID: 334200**



**Photo 3 – TR wellhead and equipment**



**Photo 4 – Silverland 31-22 Pit ID 261321,  
Fencing around needs repaired**



**Inspection Photos**  
**Location: Silverland 31-22 and Silverland 31-22 TR**  
**Location ID: 334200**



**Photo 5 – Grey spoil pile remains on location.**



**Photo 6 – Grey material noted on location pad**



**Inspection Photos**  
**Location: Silverland 31-22 and Silverland 31-22 TR**  
**Location ID: 334200**



**Photo 7 – Silverland TR Pit ID 301239**



**Photo 8 – Pieces of pit liner remain around top of pit excavation**



**Inspection Photos**  
**Location: Silverland 31-22 and Silverland 31-22 TR**  
**Location ID: 334200**



**Photo 9 – Grey material noted around pit excavation**