

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 13-6 Pad

Location ID: 334737



Photo # 9784 From entrance to location



Photo # 9785 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 13-6 Pad

Location ID: 334737



Photo # 9786 Location




Photo # 9787 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 13-6 Pad

Location ID: 334737



Photo # 9788 Location



Photo # 9789 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 13-6 Pad

Location ID: 334737



Photo # 9790 Location



Photo # 9791 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 13-6 Pad

Location ID: 334737



Photo # 9792 Location



Photo # 9793 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 13-6 Pad

Location ID: 334737



Photo # 9794 Staining near wellhead



Photo # 9795 Staining near wellhead