

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9546 From entrance to location

Photo # 9547 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9548 Location



Photo # 9549 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9550 Location



Photo # 9551 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9552 Location



Photo # 9553 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9554 Location



Photo # 9555 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9556 Location



Photo # 9557 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9558 Location



Photo # 9559 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9560 Location



Photo # 9561 Unmarked deadman

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9562 Battery sign for the GRAND VALLEY RANCH CO  
GV 88-1 production tank weathered & becoming illegible



Photo # 9563 Open ended load line

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9564 Tank lacks required labeling



Photo # 9565 Tank lacks required labeling

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



**Photo # 9566 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 9567 Debris**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 88-1 Pad

Location ID: 334734



Photo # 9568 Debris



Photo # 9569 Debris