

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad**  
**Location #: 334830**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas.**

**Section/Township/Range: 32 6S92W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad**  
**Location #: 334830**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad**  
**Location #: 334830**



**Photo # 9974 Lack of stabilization/compaction**



**Photo # 9975 Lack of stabilization/compaction**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad**  
**Location #: 334830**



**Photo # 9976 Lack of stabilization/compaction**



**Photo # 9977 Lack of stabilization/compaction**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad**  
**Location #: 334830**



**Photo # 9978 Lack of stabilization/compaction**



**Photo # 9979 Lack of stabilization/compaction**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad**  
**Location #: 334830**



**Photo # 9980 Lack of stabilization/compaction**



**Photo # 9981 Lack of stabilization/compaction**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad**  
**Location #: 334830**



**Photo # 9982 Lack of stabilization/compaction**



**Photo # 9983 Lack of stabilization/compaction**