



View of HSR-Fulenwider #4-10 repaired gully erosion looking north. 6/5/2024



View of HSR-Fulenwider #4-10 repaired gully erosion looking south. 6/5/2024



View of HSR-Fulenwider #4-10 repaired gully erosion looking east. 6/5/2024



View of HSR-Fulenwider #4-10 repaired gully erosion looking west. 6/5/2024