

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/30SESW

Location ID: 334060

Date: 6/4/2024



Jun 4, 2024 at 16:56:40
Parachute CO 81635
United States

Location Entrance – Photo #01536



Jun 4, 2024 at 16:58:29
Parachute CO 81635
United States

Wellheads – Photo #01539

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/30SESW

Location ID: 334060

Date: 6/4/2024



Separators – Photo #01538



Tank Battery – Photo #01541



Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/30SESW

Location ID: 334060

Date: 6/4/2024



Tank Battery – Photo #01543



Gas Meter/Pig Station – Photo #01537