

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/30NWNW

Location ID: 334752

Date: 6/4/2024



Jun 4, 2024 at 17:06:56
Parachute CO 81635
United States

Location Entrance – Photo #01545



Jun 4, 2024 at 17:11:48
Parachute CO 81635
United States

Wellheads – Photo #01553

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/30NWNW

Location ID: 334752

Date: 6/4/2024



Separators – Photo #01548



Tank Battery – Photo #01546

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/30NWNW

Location ID: 334752

Date: 6/4/2024



Pig Station – Photo #01550



P&A – Photo #01552

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/30NWNW

Location ID: 334752

Date: 6/4/2024



Jun 4, 2024 at 17:09:58
Parachute CO 81635
United States

Debris – Photo #01549



Jun 4, 2024 at 17:10:55
Parachute CO 81635
United States

Unprotected Soil Stockpile – Photo #01551