

# Inspection Photos

May 30th, 2024

Operator: QEP Energy Company - 10343

Location ID: 333443

Inspection Document #: 714000807

La Plata County, CO

Township: NWNW 25 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: McElvain 1-25  
Location ID: 333443

5/30/24  
+37.079659,-107.673977  
205° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of the project area taken from the northern edge facing southwest. Note: project area shows minimal establishment of desirable vegetation and appears to be affected by active grazing in the area.

API #: 067-05306



5/30/24  
+37.079621,-107.674091  
268° W





Inspection Photos  
Location Name: McElvain 1-25  
Location ID: 333443



**Photo 3.** View of stabilization/erosion issues observed forming in the southern portion of the project area.



Inspection Photos  
Location Name: McElvain 1-25  
Location ID: 333443

5/30/24  
+37.079897,-107.674479  
222° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of reference area comprised of western wheatgrass and sage brush.

API #: 067-05306