

# Inspection Photos

May 31st, 2024

Operator: Dugan Production Corporation - 25250

Location ID: 385591

Inspection Document #: 714000813

La Plata County, CO

Township: SESW 32 34N 12W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Parker 1  
Location ID: 385591



**Photo 1.** View of the project area taken from the western edge facing center.

Inspection Photos  
Location Name: Parker 1  
Location ID: 385591



**Photo 2.** Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Parker 1  
Location ID: 385591



**Photo 3.** Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west. Note: disturbance does not appear consistent with adjacent reference area and is dominated by an annual weed, cheatgrass.

Inspection Photos  
Location Name: Parker 1  
Location ID: 385591



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area comprised of smooth brome, broom snake weed and juniper.

API #: 067-06399