

Inspection Photos

API: 071-06815

Operator: WAPITI OPERATING LLC

Inspection Date: 6/10/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. This gas line was vent along the access road blowing gas in the direction of the road which is a safety concern.

