

Inspection Photos

API: 071-06929

Operator: WAPITI OPERATING LLC

Inspection Date: 6/10/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos




Photo 1. Facing southeast toward the well.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing northwest at the location. The pipe fence around this gas line needs to be repaired.



Inspection Photos



Photo 3. Facing northwest at the location. There are two going across the site creating unnecessary disturbance. The road to the left and middle of the location need to be reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06929 | Date: 6/10/2024