

# Inspection Photos

Location: 321956

Operator: PELICAN HILL OIL & GAS INC

InspectionDate:5/30/2024

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing southeast toward the location. The areas circled consist mostly of undesirable weeds. Other light colored areas are bare of vegetation.





## Inspection Photos



**Photo 2.** Drone aerial photo facing east toward the location..





## Inspection Photos



**Photo 3.** Drone aerial photo facing north toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321956 | Date: 5/30/2024



## Inspection Photos



**Photo 4.** Drone aerial photo facing west toward the location.





## Inspection Photos



**Photo 5.** Drone aerial photo facing south toward the undisturbed reference area.





## Inspection Photos



**Photo 6.** Facing north at the location, A 100 ft. tape measure shows size of the area which has insufficient perennial vegetation cover.





## Inspection Photos



**Photo 7.** Facing east at the location, A 100 ft. tape measure shows size of the area which consists mostly of undesirable weeds (kochia).





## Inspection Photos



**Photo 8.** View of vegetation cover shows mostly undesirable weeds (Kochia).





## Inspection Photos



**Photo 9.** Facing southeast. This area is approximately 15x3 ft. with no vegetation cover.





## Inspection Photos



**Photo 10.** Facing southwest toward the beginning of the transect conducted at the location.



**Photo 11.** Facing northeast toward the end of the transect conducted at the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321956 | Date: 5/30/2024



## Inspection Photos



**Photo 12.** Facing southwest toward the beginning of the transect conducted at the location.



**Photo 13.** Facing northeast toward the end of the transect conducted at the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321956 | Date: 5/30/2024



## Inspection Photos



**Photo 14.** Facing northwest toward the beginning of the transect conducted at the reference area.



**Photo 15.** Facing southeast toward the end of the transect conducted at the reference area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321956 | Date: 5/30/2024



## Inspection Photos

## Cover Data

Date: 5/31/24

Inspected By: Ryan Costa

Location/Operator:

# APT

017-07634

Pelican Hill Oil Gas

[illegible]

2nd= second hit; P= plant species present but not hit



## COLORADO

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Loc:321956 | Date: 5/30/2024