

# Inspection Photos

05/30/2024

**Operator:** CAERUS PICEANCE LLC - 10456

**Location ID:** 335939

**Inspection Doc:** 696205852

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335939



**Photo 1:** Photos 1-2 taken from the east end of the Location. Photo provides an overview of the Location from south, southwest, northwest to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335939



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335939



**Photo 3:** Fence on east end of the WPS in disrepair.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335939



**Photo 4:** Signage at tanks/facility on south end of the Location not observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335939



**Photo 5:** Photos examples showing lines at tanks missing required cap/plug.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335939



May 30, 2024



May 30, 2024

**Photo 6:** Photos taken from the interim areas on the east and south end of the Location. Reclamation appears to be progressing towards 1003 standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources