

Inspection Photos

05/30/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335904

Inspection Doc: 696205854

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335904



Photo 1: Photos taken from the “frac pad” on the northwest end of the Location. Photo provides an overview of the Location. Ongoing/continuous drilling operations are not occurring and records show that the Rig was released from the Location on 6/7/2022. Last well to be completed was produced 9/12/2022. Interim reclamation outstanding on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335904



Photo 2: Photos 2-3 taken from the east end of the Location. Photos provide an overview from southeast, south, west to northwest. See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335904



Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335904



Photo 4: Photo shows cuttings trench on the south end of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335904



Photo 5: Photo shows wells on the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335904



Photo 6: Photo shows conductors/cellars remaining on Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335904



Photo 7: Photos 7-8 taken from the northwest end of the “frac pad” section of the Location. Photos provide an overview of the frac pad from northeast, east, south to southwest. Areas require reclamation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335904



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources