

Inspection Photos

05/30/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 483521

Inspection Doc: 696205858

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 483521



Photo 1: Photo shows conductors/cellars on Location. Plates observed stored to the side rather than on top of conductors- reclamation specialist replaced plates to top of conductors. Fencing/covers not installed at conductors.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 483521



Photo 2: Location signage missing from entrance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources