

Final Reclamation and Stormwater Inspection

Date: 6/10/24

Operator: Noble Energy Inc - 100322

Location ID: 329443

Inspection Document #: 713900672

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Reinick 9-7
Location ID: 329443



Photo 1. The photo was taken at the entrance to the well location facing Southeast. The photo illustrates the access road entrance and culvert remain.



Photo 2. The photo was taken at the entrance to the well location facing Southeast. The photo illustrates the access road entrance to the well location.

Inspection Photos
Location Name: Reinick 9-7
Location ID: 329443



Photo 3. The photo was taken at the well location facing North. The photo illustrates pasture vegetation has reached the reference state.

Photo 4. The photo was taken at the well location facing East. Refer to the comment for photo 3.

Inspection Photos
Location Name: Reinick 9-7
Location ID: 329443



Photo 5. The photo was taken at the well location facing South. Refer to the comment for photo 3.

Photo 6. The photo was taken at the well location facing West. Refer to the comment for photo 3.

Inspection Photos
Location Name: Reinick 9-7
Location ID: 329443



Photo 7. The photo was taken at the tank battery location. The photo illustrates the tank battery remains active for another well location.

Inspection Photos
Location Name: Reinick 9-7
Location ID: 329443



Photo 8. The reference photo was taken near the well location facing North. The photo illustrates reference areas are dominated by Saltgrass, Smooth brome, Foxtail barley, etc.