



KT Resources LLC
 WRD Federal 30-44
 Location ID: 316153



Calibration overdue

Relief riser protection cap blown

**KT Resources LLC
WRD Federal 30-44
Location ID: 316153**



Stained soil



When replaced additional information is required

**KT Resources LLC
WRD Federal 30-44
Location ID: 316153**



Location from Northwest corner

Location from Southwest corner

**KT Resources LLC
WRD Federal 30-44
Location ID: 316153**



Location from Southeast corner

Location from Northeast corner