

Inspection Photos

06/4/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311852

Inspection Doc: 696205870

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311852



Photo 1: Photo shows unused equipment remains improperly stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311852



Photo 2: Photo taken from the cut slopes of the Location. BMPs to minimize erosion and degradation remain missing from the cut slopes on the northeast and northwest end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311852



Photo 3: Stained soils remain evident at the wells.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311852




Photo 4: Photos taken from the interim areas of the Location. Photos examples showing Halogeton germination (small green plants, basal) on the Location- ongoing weed management efforts have not occurred, or have been insufficient.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources