

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad

Location ID: 335487



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas & in close proximity
to Bald Eagle Roost site.**

Section/Township/Range: 31 6S94W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad
Location ID: 335487



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad
Location ID: 335487



Photo # 648 Lack of stabilization/compaction



Photo # 649 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad
Location ID: 335487



Photo # 650 Lack of stabilization/compaction



Photo # 651 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad
Location ID: 335487



Photo # 652 Lack of stabilization/compaction



Photo # 653 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad
Location ID: 335487



Photo # 654 Lack of stabilization/compaction



Photo # 655 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad
Location ID: 335487



Photo # 656 Lack of stabilization/compaction



Photo # 657 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC POTTER RWF 532-31 Pad

Location ID: 335487



Photo # 658 Lack of stabilization/compaction