

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403823804

Date Received:

06/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mattorano, Michael

575-445-6704/505-652-0416

mmattorano@wapitienergy.com

Madison, Randy

575-445-6706/575-420-1120

rmadison@wapitienergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601114

Inspection Date: 06/11/2024

FIR Submit Date: 06/11/2024

FIR Status: _____

Inspected Operator Information:

Company Name: WAPITI OPERATING LLC

Company Number: 10351

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqtr: NWNE Sec: 27 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.060330 Longitude: -104.764550

FACILITY - API Number: 05-071- -00 Facility ID: 412161

Facility Name: VPRC CENTRAL FACILITY
UNIT C-3 Number: _____

Qtrqtr: NWNE Sec: 27 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.060330 Longitude: -104.764550

CORRECTIVE ACTIONS:

1 CA# 195811

Corrective Action: Comply with Rule 903.d.(2)
Immediately cease venting.
Submit form 4 to report gas venting.

Date: 06/13/2024

Response: CA COMPLETED

Date of Completion: 06/10/2024

Operator Comment: The drip was venting do to an animal bumping the valve handle and opening the valve. Upon notification the valve was closed and a plug put in it to prevent this from happening again. Do to the low pressure on that line I estimate the volume vented to be 10 MCF. It was a minimal amount vented, because it did not show up on any of

our SCADA reading. See attached gas analysis.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Also see attached a picture of the correction made on the lid on the valve box.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy L. Madison

Signed: _____

Title: HSE & Reg. Specialist, Sr

Date: 6/13/2024 9:45:45 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403823830	Gas Analysis
403823832	Photo #1

Total Attach: 2 Files