

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403823804

Date Received:

06/13/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mattorano, Michael</u>	<u>575-445-6704/505-652-0416</u>	<u>mmattorano@wapitienergy.com</u>
<u>Madison, Randy</u>	<u>575-445-6706/575-420-1120</u>	<u>rmadison@wapitienergy.com</u>

### ECMC INSPECTION SUMMARY:

FIR Document Number: 713601114

Inspection Date: 06/11/2024

FIR Submit Date: 06/11/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: WAPITI OPERATING LLC

Company Number: 10351

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

### LOCATION - Location ID: \_\_\_\_\_

Location Name: \_\_\_\_\_ Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 27 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.060330 Longitude: -104.764550

### FACILITY - API Number: 05-071- -00 Facility ID: 412161

Facility Name: VPRC CENTRAL FACILITY Number: \_\_\_\_\_  
UNIT C-3

Qtrqtr: NWNE Sec: 27 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.060330 Longitude: -104.764550

### CORRECTIVE ACTIONS:

1 ☒ CA# 195811

Corrective Action: Comply with Rule 903.d.(2)  
Immediately cease venting.  
Submit form 4 to report gas venting.

Date: 06/13/2024

Response: CA COMPLETED

Date of Completion: 06/10/2024

Operator Comment: The drip was venting do to an animal bumping the valve handle and opening the valve. Upon notification the valve was closed and a plug put in it to prevent this from happening again. Do to the low pressure on that line I estimate the volume vented to be 10 MCF. It was a minimal amount vented, because it did not show up on any of

our SCADA reading. See attached gas analysis.

ECMC Decision: Approved

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Also see attached a picture of the correction made on the lid on the valve box.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy L. Madison

Signed: \_\_\_\_\_

Title: HSE & Reg. Specialist, Sr

Date: 6/13/2024 9:45:45 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403823804	FIR RESOLUTION SUBMITTED
403823830	Gas Analysis
403823832	Photo #1

Total Attach: 3 Files