

Inspection Photos
Location Name: REI H 17-28D
Location ID: 306737



Photo 1: Wellhead Sign



Photo 2: TA Wellhead

Inspection Photos
Location Name: REI H 17-28D
Location ID: 306737



Photo 3: Unused equipment

Photo 4: Tank Battery Sign

Inspection Photos
Location Name: REI H 17-28D
Location ID: 306737



Photo 5: Debris



Photo 6: Debris

Inspection Photos
Location Name: REI H 17-28D
Location ID: 306737



Photo 7: Debris



Photo 8: debris

Inspection Photos
Location Name: REI H 17-28D
Location ID: 306737



Photo 9: Unused equipment/risers



Photo 10: Unused equipment, No LOTO

Inspection Photos
Location Name: REI H 17-28D
Location ID: 306737



Photo 11: Unused equipment, No LOTO



Photo 12: Unused equipment, No LOTO

Inspection Photos
Location Name: REI H 17-28D
Location ID: 306737



Photo 13: Unused equipment, No LOTO