

# Complaint Inspection

Date: 6/10/24

Operator: KP Kauffman Company Inc - 46290

Location ID: 317748

Inspection Document #: 713900679

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: McCrumb-62N66W 17NWSE  
Location ID: 317748



**Photo 1.** The photo was taken at the tank battery location facing East. The photo illustrates weeds noted in the previous FIR and complaint were mowed and sprayed around equipment as well as the Operator tank battery sign.

**Photo 2.** The photo was taken at the tank battery location facing South. Refer to the comment for photo 1.

Inspection Photos  
Location Name: McCrumb-62N66W 17NWSE  
Location ID: 317748



**Photo 3.** The photo was taken at the tank battery location facing East. Refer to the comment for photo 1.



**Photo 4.** The photo was taken at the active pit facing North. The photo illustrates areas not in use that have not been reclaimed with evidence of gravel remaining and no vegetation growth.

Note - The pit appears to be inactive.

## Inspection Photos

Location Name: McCrumb-62N66W 17NWSE

Location ID: 317748



**Photo 5.** The photo was taken at the well location facing South. The photo illustrates are large amount of unmanaged Curly dock growing within the interim area.



**Photo 6.** The photo was taken at the well location facing Southwest. The photo illustrates unmanaged weed debris and actively growing Curly dock at the location.

## Inspection Photos

Location Name: McCrumb-62N66W 17NWSE

Location ID: 317748



**Photo 7.** The photo was taken at the well location facing South. The photo illustrates an example of a noxious weed, Musk thistle, as well as Curly dock and cheatgrass being unmanaged at the location.

**Photo 8.** The photo was taken at the tank battery location facing Southeast. The photo illustrates unmanaged weed debris on the location.

Inspection Photos  
Location Name: McCrumb-62N66W 17NWSE  
Location ID: 317748



**Photo 9.** The photo was taken at the tank battery location facing East. The photo illustrates an unknown, unmarked riser to the South of the tank battery.