

Inspection Photos


Location: Laramie Energy LLC My Way Ranch Federal 6-11 Pad

Location ID: 334542

Date: 6/11/2024



Entrance to location - Photo #02339



Location - Photo #02346

Inspection Photos

Location: Laramie Energy LLC My Way Ranch Federal 6-11 Pad

Location ID: 334542

Date: 6/11/2024



Well heads - Photo #02340



Separators - Photo #02342

Inspection Photos

Location: Laramie Energy LLC My Way Ranch Federal 6-11 Pad

Location ID: 334542

Date: 6/11/2024



Separators - Photo #02343



Separators - Photo #02344

Inspection Photos

Location: Laramie Energy LLC My Way Ranch Federal 6-11 Pad

Location ID: 334542

Date: 6/11/2024



Tank battery - Photo #02345



Holes in liner - Photo #02357

Inspection Photos

Location: Laramie Energy LLC My Way Ranch Federal 6-11 Pad

Location ID: 334542

Date: 6/11/2024



Hole in liner - Photo #02358



Northeast corner of location - Photo #02365