

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246



Photo # 778 From entrance to location



Photo # 779 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246



Photo # 780 Location



Photo # 781 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246



Photo # 782 Location



Photo # 783 Wellhead sign faded & becoming illegible/does not comply CECMC rules

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246



Photo # 7 From inspection 708903278 conducted on 03/14/2024 Unused equipment



Photo # 784 Unused equipment

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246



**Photo # 785 Unused equipment/ECD disconnected & not in use**