

Interim Reclamation and Stormwater Inspection

Date: 6/10/24

Operator: Noble Energy Inc - 100322

Location ID: 329434

Inspection Document #: 713900689

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Smith-64N64W 9SWNW

Location ID: 329434



Photo 1. The photo was taken at the tank battery location facing South. The photo illustrates the location sign indicating the location is shut in.



Photo 2. The photo was taken at the tank battery location facing East. The photo illustrates an overview of the tank battery location.



Photo 3. The photo was taken at the tank battery location facing West. The photo illustrates stained soil at the tank battery location.

Inspection Photos
Location Name: Smith-64N64W 9SWNW
Location ID: 329434



Photo 4. The photo was taken at the tank battery location facing Southwest. The photo illustrates what appears to be erosion on the south side of the tank battery location.