

Final Reclamation and Stormwater Inspection

Date: 06/11/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 330206

Inspection Document #: 708201314

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Photo 1. Facing north. The reclaimed well location is not progressing towards final reclamation standards and regulations. Alfalfa does not appear to be establishing over the reclaimed areas.

Inspection Photos
Location Name: Brown 3-14
Location ID: 330206



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Brown 3-14
Location ID: 330206



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: Brown 3-14
Location ID: 330206



Photo 4. Facing west; see comments in Photo 1.



Photo 5. Pothole from flowline removal does not appear reflect of adjacent crop.

Inspection Photos
Location Name: Brown 3-14
Location ID: 330206



Photo 6. Gravel/road base remains at irrigation ditch crossing.

Inspection Photos
Location Name: Brown 3-14
Location ID: 330206



Photo 7. Adjacent reference area photo taken south of the location.