

# Interim Reclamation and Stormwater Inspection

Date: 06/11/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 423594

Inspection Document #: 708201315

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Bickling PC D 02-33Tank  
Location ID: 423594



**Photo 1.** Location signage is not legible. Kochia and cheatgrass also observed.



Inspection Photos  
Location Name: Bickling PC D 02-33Tank  
Location ID: 423594



**Photo 2.** Eastern interim area; kochia and curly dock observed in the reclaimed areas.



Inspection Photos  
Location Name: Bickling PC D 02-33Tank  
Location ID: 423594



**Photo 3.** CO List B Noxious Weed - canada thistle- observed on the eastern interim areas.





**Photo 4.** Northern portions of the interim areas appear to have desirable vegetation present.



Inspection Photos  
Location Name: Bickling PC D 02-33Tank  
Location ID: 423594



**Photo 5.** Northwest corner of the interim areas consist primarily of CO List B Noxious Weed- canada thistle, and smooth brome.



Inspection Photos  
Location Name: Bickling PC D 02-33Tank  
Location ID: 423594



**Photo 6.** West of tank battery, interim areas have CO List B Noxious Weed- canada thistle infestation.



Inspection Photos  
Location Name: Bickling PC D 02-33Tank  
Location ID: 423594



**Photo 7.** Continued from Photo 6, curly dock, kochia, and CO List B Noxious Weed- canada thistle pictured.



Inspection Photos  
Location Name: Bickling PC D 02-33Tank  
Location ID: 423594



**Photo 8.** Hydrocarbon staining at VST.



Inspection Photos  
Location Name: Bickling PC D 02-33Tank  
Location ID: 423594



**Photo 9.** Hydrocarbon staining at VST.