

Final Reclamation and Stormwater Inspection

Date: 06/11/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 322958

Inspection Document #: 708201316

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Andre 2-3E
Location ID: 322958



Photo 1. The former well location is not progressing towards Rule 1004 standards and regulations with evidence of undesirable vegetation (kochia) and areas of exposed/bare soil. Additional reclamation activities are required.

Inspection Photos
Location Name: Andre 2-3E
Location ID: 322958



Photo 2. Facing west; see comments in Photo 1.

Inspection Photos
Location Name: Andre 2-3E
Location ID: 322958



Photo 3. The former tank battery location is predominantly undesirable vegetation (kochia). Some desirable vegetation was observed (sand dropseed, western wheatgrass) though it doesn't appear dense enough to displace the undesirable vegetation.

Inspection Photos
Location Name: Andre 2-3E
Location ID: 322958



Photo 4. Facing west; see comments in Photo 3.

Inspection Photos
Location Name: Andre 2-3E
Location ID: 322958



Photo 5. Facing north. It appears that the southern portion of the tank battery reclaim is being used as a herbicide washout.



Photo 6. The western portion of the former tank battery location does not appear to have been contoured/graded to prevent the accumulation of stormwater on the access road.

Inspection Photos
Location Name: Andre 2-3E
Location ID: 322958



Photo 7. Facing east; see comments in Photo 6.