

Inspection Photos

Location Name: CAERUS PICEANCE LLC, BATTLEMENT MESA-67S95W/34NWNW

Location ID: 334179

Date: 6/11/2024



Jun 11, 2024 at 11:30:52
Parachute CO 81635
United States

Separators – Photo #01719



Jun 11, 2024 at 11:29:01
Parachute CO 81635
United States

Tank Battery – Photo #01714

Inspection Photos

Location Name: CAERUS PICEANCE LLC, BATTLEMENT MESA-67S95W/34NWNW

Location ID: 334179

Date: 6/11/2024



Battery Fencing Damaged – Photo #01715



Stored Equipment/Supplies – Photo #01716

Inspection Photos

Location Name: CAERUS PICEANCE LLC, BATTLEMENT MESA-67S95W/34NWNW

Location ID: 334179

Date: 6/11/2024



Unsecured Separator – Photo #01720



Cut Slope Degradation/Damaged Fencing – Photo #01718