



Inspection Photos
Location Name: A27
Remediation Project #: 9748
Spill/Release ID: 446199
Inspection Date: June 2, 2024

Secondary containment
surrounding fuel tank in
disrepair.

Jun 4, 2024 10:39:23 AM
+39.6981N -108.1436W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: A27
Remediation Project #: 9748
Spill/Release ID: 446199
Inspection Date: June 2, 2024

Trash and debris
adjacent to the water
treatment plant.

Jun 4, 2024 11:20:06 AM
+39.6979N -108.1437W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: A27

Remediation Project #: 9748

Spill/Release ID: 446199

Inspection Date: June 2, 2024

Trash and debris within
East Stuart Gulch down
gradient of the water
treatment plant.

Jun 4, 2024 10:41:47 AM
+39.6985N -108.1433W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: A27
Remediation Project #: 9748
Spill/Release ID: 446199
Inspection Date: June 2, 2024

Trash and debris within
East Stuart Gulch down
gradient of the water
treatment plant.

Jun 4, 2024 10:43:48 AM
+39.6988N -108.1433W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: A27

Remediation Project #: 9748

Spill/Release ID: 446199

Inspection Date: June 2, 2024

Trash and debris within
East Stuart Gulch down
gradient of the water
treatment plant.

Jun 4, 2024 10:44:14 AM
+39.6989N -108.1433W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: A27

Remediation Project #: 9748

Spill/Release ID: 446199

Inspection Date: June 2, 2024

Hydrocarbon odor and sheen observed within East Stuart Gulch.

Jun 4, 2024 12:09:50 PM
+39.6936N -108.1442W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: A27

Remediation Project #: 9748

Spill/Release ID: 446199

Inspection Date: June 2, 2024

Hydrocarbon odor and sheen observed within East Stuart Gulch.

Jun 4, 2024 12:09:52 PM
+39.6936N -108.1442W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: A27
Remediation Project #: 9748
Spill/Release ID: 446199
Inspection Date: June 2, 2024

Hydrocarbon odor and sheen observed within East Stuart Gulch.

Jun 4, 2024 12:09:54 PM
+39.6936N -108.1441W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: A27

Remediation Project #: 9748

Spill/Release ID: 446199

Inspection Date: June 2, 2024

Hydrocarbon odor
observed within East
Stuart Gulch.

Jun 4, 2024 12:20:14 PM
+39.6934N -108.1441W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources