

Inspection Photos
Location Name: Coalview G02-64-1HN Pad
Location ID: 438174




Photo 1: Tank Battery Sign

Photo 2: Tank Battery Sign

Location ID: 438174



Photo 3: Location from entrance




Photo 4: Unused/disconnected gas meter

Inspection Photos
Location Name: Coalview G02-64-1HN Pad
Location ID: 438174



Photo 5: Equipment



Photo 6: Equipment

Inspection Photos
Location Name: Coalview G02-64-1HN Pad
Location ID: 438174



Photo 7: Equipment



Photo 8: Sound wall in disrepair

Inspection Photos

Location Name: Coalview G02-64-1HN Pad

Location ID: 438174




Photo 9: Wellhead



Photo 10: Wellhead