

## Inspection Photos


Location: TEP Rocky Mountain LLC Bosely-67S96W/22NESE

Location ID: 334580

Date: 6/18/2024



Entrance to location - Photo #02658



Location - Photo #02668

## Inspection Photos

Location: TEP Rocky Mountain LLC Bosely-67S96W/22NESE

Location ID: 334580

Date: 6/18/2024



Well heads - Photo #02659



Separators - Photo #02665

## Inspection Photos

Location: TEP Rocky Mountain LLC Bosely-67S96W/22NESE

Location ID: 334580

Date: 6/18/2024



Tank battery - Photo #02666



Wildlife hazard - Photo #02672

## Inspection Photos

Location: TEP Rocky Mountain LLC Bosely-67S96W/22NESE

Location ID: 334580

Date: 6/18/2024



Wildlife hazard - Photo #02674



Wildlife hazard - Photo #02675

## Inspection Photos

Location: TEP Rocky Mountain LLC Bosely-67S96W/22NESE

Location ID: 334580

Date: 6/18/2024



Northwest corner of location - Photo #02677



Northeast corner of location - Photo #02680